





$-N^Q$	$\begin{matrix} z \\ y \end{matrix}$		
41225351000M	25/35	36	
41230301000M	30/30	36	
41230351000M	30/35	36	
41230401000M	30/40	36	
41230451000M	30/45	36	
41230501000M	30/50	36	
41230551000M	30/55	36	
41230651000M	30/65	36	
41230801000M	30/80	36	
41235351000M	35/35	36	
41235401000M	35/40	36	
41235451000M	35/45	36	
41235501000M	35/50	36	
41235551000M	35/55	36	
41235601000M	35/60	36	
41235651000M	35/65	36	
41235801000M	35/80	36	
41240401000M	40/40	36	
41240451000M	40/45	36	
41240501000M	40/50	36	
41240551000M	40/55	36	
41240601000M	40/60	36	
41240651000M	40/65	36	
41240701000M	40/70	36	
41245451000M	45/45	36	
41245501000M	45/50	36	
41245551000M	45/55	36	
41245601000M	45/60	36	
41250501000M	50/50	36	
41250551000M	50/55	36	
41260601000M	60/60	36	



$-N^Q$	$\begin{matrix} z \\ y \end{matrix}$		
41225350100M	25/35	36	
41230300100M	30/30	36	
41230350100M	30/35	36	
41230400100M	30/40	36	
41230450100M	30/45	36	
41230500100M	30/50	36	
41230550100M	30/55	36	
41235350100M	35/35	36	
41235400100M	35/40	36	
41235450100M	35/45	36	
41235500100M	35/50	36	
41235550100M	35/55	36	
41235600100M	35/60	36	
41235650100M	35/65	36	
41240400100M	40/40	36	
41240450100M	40/45	36	
41240500100M	40/50	36	
41240550100M	40/55	36	
41240600100M	40/60	36	
41245450100M	45/45	36	
41245500100M	45/50	36	
41245550100M	45/55	36	
41245600100M	45/60	36	
41250500100M	50/50	36	
41260600100M	60/60	36	

